

## REMARKS

Claims 1-20 are pending.

### *Preliminary Matters*

Claims 12-20 are cancelled herewith.

There is no brief description of Figures 1C and 1D.  
Figures 1C and 1D are cancelled herewith.

### *Drawing Correction*

**Figures 3B, 3C and 3D** are corrected.

The expanding segment at the top is "328", not "320".

At page 16, lines 1-4

The biasing members 338 are disposed at axially spaced apart positions about the spindle 308, and are suitably in the form of rubber bands extending through corresponding holes 342a 343a and 342b 343b in each of the ramp elements 348.


The holes at the top are "343a" and "343b", not "342a" and "342b".  
"342a" and "342b" correctly refer to the radially-extending grooves (page 14, line 14)

The axis 304 was missing from the illustration.

Claim 1-11 remain.

Favorable examination and consideration are respectfully requested.

Respectfully submitted,



Howard M. Cohn  
Reg. No. 25,808

21625 Chagrin Blvd. Suite 220  
Cleveland, Ohio 44122  
(216) 752-0955 phone  
(216) 752-0957 fax

goodyear\gy386div prelamn



